

Norwell Public Library

Structural Analysis:

Norwell Public Library
Norwell, MA

re: Geotechnical Report (by HML Associates, Geotechnical & Civil Engineers)

Hi, Stephen.

The geotechnical report indicates that the existing soils are adequate to support shallow foundations and slab-on-grade. Note that seasonal high ground water levels were found 2.0-2.5 ft below grade.

Regards,

Dan

Daniel Bonardi P.E., Principal
Daniel Bonardi Consulting Engineers
1165R Massachusetts Avenue, Suite 203
Arlington MA 02476
(t) (781) 483-3336